

1 of 2



McQuillan Envirocare Ltd

Analytical Services

Test Certificate


Certificate: Issue No:

ECTC003822

Dalradian Gold Ltd 3 Killybrack Road Omagh Tyrone BT797DG Caulside Drive New Park Industrial Estate Antrim BT41 2DV

Tel: (028) 9446 6708 Fax: (028) 9442 9580

www.mcquillancompanies.com sales@mcquillanenvirocare.com



Dear E

Analysis of your sample(s) is now complete and we have pleasure in enclosing the appropriate test report.

All analysis was completed within McQuillan Envirocare Analytical Laboratory (MCQ) unless otherwise specified. Any analysis that was subcontracted to a McQuillan Companies Approved Laboratory is indicated by 'S'. Please refer to the table at the end of your test certificate for explanations of sample deviations.

Results relate only to the items tested. This Test Certificate supersedes any version previously issued by the laboratory. It cannot be reproduced except in full and without written approval from McQuillan Envirocare Ltd.

Should you have any queries regarding this report(s) or any part of our service, please contact Sales on +44(0)28 9446 6708 who will be happy to discuss your requirements.

Thank you for using McQuillan Companies Analytical Services and we look forward to receiving your next samples.

Yours Sincerely



Lab Technician





McQuillan Envirocare Ltd

Analytical Services

Test Certificate

Page:

Certificate:

ECTC003822

Issue No:

1

2 of 2

Lab Ref	Sample Details	Sample Date	Method No.	Test	Result	Units	ACC	Lab	Sample Deviations
MCQ017012	Ditch	23/01/2015	SAM001	Suspended Solids	32	mg/l	Υ	MCQ	@

Sample Matrix: Surface Water

Analyst Comment:

Samp	le Dev	iations Legend		
Comment		Incorrect Container		
Container with Headspace provided	00	Insufficient sample volume	¢	
BOD Overdiluted, therefore result indicative only	\$	BOD Underdiluted, therefore result indicative only	#	
High Chloride concentration, COD could not be determined	§	Holding time exceeded due to sampled on date	@	
Holding time exceeded in Lab	±	Holding time exceeded due to delayed Instructions	8	