

[REDACTED]

From: [REDACTED]
Sent: 30 January 2015 17:21
To: [REDACTED]
Subject: FW: Site visit - Curraghinalt 30/1/2015
Attachments: 20150130_143727.jpg

TC 40/12 Volume 4.

Hi [REDACTED]
As discussed could you pl file and Trim
Pl print down the Photograph also to the file
TC 40/12 Volume 4.

Thanks
[REDACTED]

From: [REDACTED]
Sent: 30 January 2015 16:43
To: [REDACTED]
Cc: [REDACTED]
Subject: Site visit - Curraghinalt 30/1/2015

[REDACTED]
I visited the site this afternoon and there was a discharge of site run-off. Water was escaping under the silt fence adjacent to the gate at the bottom of the fence. The discharge was slightly discoloured and it was entering the Curraghinalt Burn. Due to the high flow in the burn there was no visible impact. I made [REDACTED] aware of the issue and he tasked [REDACTED] with getting it resolved.

[REDACTED]

Water Quality Inspector
Lisnamallard House,
Old Mountfield Road,
OMAGH
BT79 7EG
(028) 8225 6215

